
CALAINA AND AND THE AND	ATER TESTING FORM	Page _ /_ of <u>/</u>
Sewershed: PATAPSCO	Company: Savin Engineers	Date: <u>//~3-09</u>
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: Dyed Water: χ	Dry: 🔀 Damp: Wet:	
Manhole ID: <u>\$4/72 ~ 006 m4</u>	Test ID: <u>D/041 - 145 / x0008</u>	Notifications Made: (Residents, Fire, 311
FIRST FLOODED THIS STORM LINE S4:112 00 11H OVE DEPLOYED WERE (THIS IS THE ONE THAT SMOKES)	4803 4803 4803 4805 ARCOYES DYE IN THIS CONTROL OF SAME CONTRO	raph Numbers)

CITY OF BALTIMORE WET W SMOKE AND DYED WA								Page 2 of 3	
Sewershed: PATAPSCO			Company: SAVIN				Date: <u>11/3/09</u>		
Test to	be Performed:			Ground	Condition			Supervisor:	ιΤΑΜ
Smoke: Dyed Water: X			Dry: X Damp: Wet:				<u> </u>		
Manhole ID: <u>S41I2 006MH</u>			Test ID: <u>D1041-145</u>				Notifications Made: X (Residents, Fire, 311)		
	Sketch: (Showons, Street Nam						_		
Defect		, 5		Source			Drainage		Photo
No.		Address		Туре	Location	Sector	Area	Severity	Number
1	4603 VIR	GINIA AVE		12	11	1	10000	NA	1
	1005 VIII	JINIA AVE		14			10000	IVA	
	-			OBSER\	ATION	CODES			
	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved		
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods		
03	Cleanout	Paved Other		Moderate	12	Catch Basin/Inlet	Alley		
04	Downspout	Driveway		Major	13	Storm Manhole	Golf Course		
	Area Drain	Sidewalk			14	Storm Ditch	Other		
06	Driveway Drain	Curb			15	Excavation			
07	Stairwell Drain	Yard- Front			16	Other			
08	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>3</u>	
Sewershed: PATAPSCO	Company: Savin Engineers	Date: <u>11/3/09</u>
Test to be Performed:	Ground Condition:	Supervisor: Joe
	Ground Gorialion.	Mirabito
Smoke: Dyed Water: X	Dry: X Damp: Wet:	Mirabito

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



D1041-145-OB01-P01